

## **Project Update in Photos - June 10, 2013**


Klaus Johansson of Suite 4502 has shared the following photos of the window replacement project as it progressed through their suite. He requests that the photos not be copied or published outside this project update without his prior consent. Please respect his wishes.

Thank you, Klaus.

### **Assembly of the staging platform – Late April 2013**



S







First week in May 2013








## Hallway Protection







Platform anchor to bedroom wall



Beginning of window installation








**Edge of old window**



**Edge of new triple glazed window**





Old vs. new glass



On the staging platform






**New glass above**



**New glass and no glass**









Suction cups for holding glass



Exterior like a mirror





Week after installation – platform moved down





**New glass above**



**Old glass below**





First week of June





